

Field Remedy: 1466

Subject: **Header Seal Retention Fix - Water ingress**

Models: **Engines:** **Option:**

Speedster 2000...2002 Z22SE

Complaint: Water ingress at strong rain fall.

Cause: Insufficient sealing.

Production: With Speedster Turbo / VX220 Tornado the new weatherstrip front roof frame has been introduced in production.

Remedy:

In case of customer complaint replace the weatherstrip front roof frame against the new improved weatherstrip front roof frame.

For replacement of weatherstrip front roof frame
- see working procedure "Weatherstrip for Front Roof Frame, Replace",
group "C", Service Instruction Speedster / VX220.

Spare-Parts:	Qty:	Part-No.:	Catalog-No.:
Seal, Header Rail, Front	1	9198484	48 01 531
Clip, Seal, Front	2	9197974	48 00 974

Labour Times:	TC:	Hours:
T 8 146 60 Replace Weatherstrip front Roof Frame	92	SA

The costs for this repair will be covered for vehicles not older than 3 years and a mileage lower than 100.000 Km.
The regular warranty procedure should be used for claiming Set-up-time.

FunctionalGroup: A - Body

Complaint Group: 10 - Leakages

Trouble Code: Non