

# Field Remedy: 1469

**Subject:**     **Headlamp - Fogging**

**Models:**                               **Engines:**     **Option:**

VX220 2000...,Speedster 2000...     All,All

**Complaint:**     Condensation in the headlamps.

**Cause:**             Due to physical reasons it is possible that condensation in the headlamps appears.

**Production:**

## Remedy:

Information has been updated. Please view TSB 1598

**FunctionalGroup:**     N - Electrical Equipment

**Complaint Group:**     12 - Misting

**Trouble Code:**         None