## Field Remedy: 1507

Subject: Battery - Cable at terminal loose

Models:	Engines:	Option:
All 2001,5	All	None
Complaint:	Engine start problem.	
Cause:	Disconnected Battery cable after storage not tightened correctly.	
Production:		

## **Remedy:**

Check the battery terminals for correct tightening during PDI. This operation is included in PDI since MY 2001,5.

FunctionalGroup:	J - Engine,N - Electrical Equipment	
Complaint Group:	04 - Electrical failures,21 - Poor Startability,24 - Wrong or not mounted	
Trouble Code:	None	