Field Remedy: 1673

Subject:	Interior Trim - Painted interior trim surfaces damaged by air refreshers	
oubjeet.	interior trini i united interior trini ouridoeo duniuged by un refreciero	

Models:	Engines:	Option:
All All	All	None
Complaint: radio, da Painted s Cause: vehicles.		er complains about loosing paint on interior trim components like ashboard, switches and the center console. surfaces will be attacked and damaged by usage of air refreshers in . Air refreshers contain aggressive ingredients therefore it should be get in direct contact with painted surfaces.

Production:

Remedy:

Customers have to be informed about this concern. Often a hint is even printed on the air refresher packaging that every contact with painted surfaces has to be avoided. Parts damaged by usage of air refreshers in the vehicle will not be accepted by warranty.

- FunctionalGroup: N Electrical Equipment
- **Complaint Group:** 07 Foreign Material or Fluid

Trouble Code: None