

# Field Remedy: 1507

**Subject:**     **Battery - Cable at terminal loose**

**Models:**       **Engines:**     **Option:**

All 2001,5...     All               None

**Complaint:**     Engine start problem.

**Cause:**         Disconnected Battery cable after storage not tightened correctly.

**Production:**

## Remedy:

Check the battery terminals for correct tightening during PDI.  
This operation is included in PDI since MY 2001,5.

**FunctionalGroup:**     J - Engine,N - Electrical Equipment

**Complaint Group:**     04 - Electrical failures,21 - Poor Startability,24 - Wrong or not mounted

**Trouble Code:**       None