

# Field Remedy: 1678

**Subject:** [New P&A engines with ECU - TC P0602 \(44\)](#)

**Models:**      **Engines:**      **Option:**

All              All              None

**Complaint:**      SVS on and TC P0602 (44) stored after programming of ECU

**Cause:**              Engines supplied from P&A are being completed with a production ECM, which is not usable for P&A purposes, because they are built up for the assembly plants.

**Production:**      Not affected

## Remedy:

Please use the old ECM in case of an engine exchange. The new ECM coming with the new engine has to be assembled to the old engine, which will be returned to the warranty return center or the engine core return process.

**FunctionalGroup:**      J - Engine

**Complaint Group:**      04 - Electrical failures

**Trouble Code:**              TC P0602 (44)