

Field Remedy: 1532

Subject: Engine - Broken Timing Chain

Models:

Astra-G 2000...2002,VX220
2000...2002,Speedster
2000...2002,Zafira
2000...2002,Vectra-B
2000...2001,Vectra-C 2002

Engines:

Z22SE,Z22SE,Z22SE,Z22SE,Z22SE,Z22SE

Option:

Complaint: Engine damaged by broken timing chain.

Cause: Missing or insufficient lubrication of the timing chain.

Production: Modified tensioner and lubrication nozzle have been introduced in production as of the following engine-No: 11065400 (March 2002).

Remedy:

In case of customer complaint please use for the necessary repair the timing chain kit (Part/Cat.-No. 12577385/ 5636400). This kit contains the modified timing chain and tensioner.

Spare-Parts:	Qty:	Part-No.:	Catalog-No.:
Set-Drive Parts	1	12 577 385	56 36 400

FunctionalGroup: J - Engine

Complaint Group: 01 - Broken or Cracked

Trouble Code: