Brake System, Inspect for Leaks

 Install brake pedal tensioner KM-325 between seat frame and brake pedal, then wait 10 minutes before inspecting brake system

