

Field Remedy: 1635

Subject: Destinator 2.0 - Mobile navigation system for pocket PCs - GPS (Global Positioning System) inoperative

Models: **Engines:** **Option:**

All 2001... All None

Complaint: GPS without function.

Cause: Vehicle is equipped with Solar Reflect Windscreen (heat reflective).

Production:

Remedy:

In case of solar reflective windscreen use GPS-Receiver-Extension-Cable (Part-No.: 93178907 / Cat.-No.: 17 30 160) and assemble the receiver on the rear-window shelf.

FunctionalGroup: N - Electrical Equipment

Complaint Group: 13 - No/Poor Function

Trouble Code: None