Field Remedy: 1423 Page 1 of 1

Field Remedy: 1423

Subject: Cable damages - Marten bite attacks

Models: Engines: Option:

All All

Complaint: Cable damages with different origin

Cause: Martenbites in engine compartment

Production:

Remedy:

In case of marten attacks it seems to be useful to wrap the replaced and likewise other exposed cables with plastic grooved tubes. Please see partnumbers below.

Parts:	Part-No.:	CatalogNr.:
5m roll, tube grooved, 10mm outer diameter	90 443 557	12 88 103
5m roll, tube grooved, 18mm outer diameter	90 443 558	12 88 104

FunctionalGroup: N - Electrical Equipment

Complaint Group: 01 - Broken or Cracked

Trouble Code: