


Brake Master Cylinder and Servo

A tandem master cylinder with a servo is installed.



T 9292

- **Service**

Repair of the master cylinder is not envisaged.