


Transmission Shift Linkage – Illustration

Illustration shown for reference only.

Individual components of shift linkage are not serviceable.



T 0483