

## Explanation of Painting Stages I, II and III Allowances

The time allowances for major and combination painting operations are divided into painting stages.

Paint stage	Description
I	<b>Painting new components</b> <ul style="list-style-type: none"><li>o Top-coat complete surface</li><li>o Fill complete surface</li><li>o Partially apply filler on repaired parts</li></ul>
II	<b>Painting surfaces</b> <ul style="list-style-type: none"><li>o Top-coat complete surface, including small improvements (without filler application)</li></ul>
III	<b>Repair</b> <ul style="list-style-type: none"><li>o Top-coat complete surface</li><li>o Fill working surface</li><li>o Partially apply putty to up to 50% of surface to be painted in operation area.</li></ul>